Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3651	(belt near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:47
L2	1	1 and spring near2 expansion near5 belt near3 (force load stress strain)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:44
L3	10	1 and spring near2 expansion	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:45
L4	3	1 and spring near2 expansion.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:46
L5	512	1 and spring.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:47
L6	75	1 and (spring near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:47
L7	31	1 same (spring near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:48
L8	10	6 and magnet.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:49
L9	7	7 and magnet.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/11/21 17:49